

Zr-Al PHASE DIAGRAM

WEIGHT PERCENT ALUMINUM

0 10 20 40 60 80 100




FIG. 5